

# Gulfstream GIVSP S/N 1321 N905LP

Date of Manufacture (CofA): October 1997 Entry Into Service: July 1998



# **Aircraft Highlights**

Quality Pedigree USA Based / N-Registered Engines Enrolled on JSSI APU Enrolled on MSP 12 Passenger Configuration Aft Galley New Paint in 2018 Complete Interior Refurbishment in 2021 Upgraded Gogo L5 Avance Wi-Fi WAAS/LPV Upgraded -150 APU



Engine 2

**Airframe:** (As of November 2024) 8,990 Hours Since New 4,683 Landings

**APU:** Honeywell GTCP36-150(G) Enrolled on MSP 5,737 Hours Engines: Rolls-Royce TAY611-8 (GIV)
Engines Enrolled on JSSI
Overhaul/20 Year Calendar c/w January
2017 at 7,195 Hrs by Rolls-Royce
Engine 1 8,839 SNEW 4,602 CSN

8,839 SNEW 4,602 CSN































**Exterior:** Stripped & New Paint September 2018 at Standard Aero, Springfield, IL Overall Matterhorn White

Interior: Complete Interior Refurbishment in 2021 by VIP Completions

12 Passenger Configuration with Aft Galley Forward Cabin 4 Single Club Seats

Mid Cabin 2 Single Seats and 4 Place Divan

Aft Cabin 2 Single Seats opposite a wood credenza

- Crew jump seat certified for taxi, take off, and landing
- Forward crew lavatory with stowable sink assembly



### **Avionics:**

Dual Honeywell SPZ-8400 6-Tube EFIS Flight Director

Dual Honeywell AZ-810 Air Data Computer **Triple** Collins VHF-422D Communication

Dual Collins VIR-432 Navigation

Dual Collins DME-442 Dual Collins ADF-462

Dual Honeywell CDU-810 Display Units

Collins HF-9000 HF Communication w/ Selcal Dual

Dual Collins TDR-94D Mode S Transponder w/ Enhanced Flight ID &

Dual Honeywell AA-300 Radio Altimeter Dual Honeywell LaserefIRS w/ Single AHRS

Dual Honeywell NZ-2010 FMS w/ 6.1 Software & Dual GPS

Honeywell SPZ-8400 Autopilot

ADS-B Out v2

Honeywell Primus 880 Color Radar w/ 24" Antenna Honeywell GNS-XLS Long Range Nav (3rdFMS)

#### Additional Features:

FMS 6.1 w/ SBAS/WAAS/LPV

Honeywell TCAS II w/ Change 7.1 FAR

Part 135 Equipped

Honeywell Mark V EGPWS w/ Wind

shear Alert & RAAS

Honeywell MCS-6000 SATCOM

AircellIridium Access II Dual-Channel

Flight Phone

RVSM & RNP-5/RNP-10 Compliant

8.33 KHz Spacing & FM Immunity

BFG GH-3000 Electronic Standby

Instrument System

Garmin GI-275 SFD

Vision Safe Emergency Vision Assurance System (EVAS)

Kollsman3 in1 Cabin Pressure Indicator

Dual Collins RTU-4220 Radio Tuning

Fairchild/Loral A-100 CVR

Fairchild/Loral F-1000 Digital FDR

**Dual Radar Controllers** 

Artex 406 Satellite ELT

Pulse Lights & Logo Lights

Honeywell DL-950 Data Loader

### **Additional Equipment:**

ASC 464 DL950 Data Loader Installation **ASC 465C** APU 36-150(G) Installation

Water Line Ribbon Heater-Upgrade ASC 469/469A

(Dual NZ) FMS 6.1 NZ2010 System w/ SBAS/WAAS/LPV GPS **ASC 477A** 

ASC 480 TCAS 7.1 Installation

Gust Lock Throttle Interlock -Retrofit ASC 501B

ADS-B Out v2 Installation ASC 502





## **Aircraft Programs:**

**Engines Enrolled on JSSI** APU Enrolled on Honeywell MSP

Maintenance Inspections		
Inspection	Last Performed	Next Due
12 Month	Feb 2024	Feb. 2025
24 Month	June 2024	June 2026
36 Month	June 2023	June 2026
48 Month	June 2024	June 2028
72 Month	June 2020	June 2026
96 Month	-	March 2026
192 Month	April 2012	April 2028